East End Pond – Risk Assessment

The pond is situated within a children's play park with open access from all sides. It is a seasonal pond with water levels rising and falling throughout the year dependant upon the underlying water table and rainfall. Typically, the pond is dry through the months of June to October with water levels rising and falling through the months of November to May. The general public have had access to the facility since 1984 with no known or recorded health and safety incidents. The pond does freeze over in winter.

The pond is designated and maintained as a wildlife feature rather than a sports and leisure facility.



East End Pond – Risk Assessment

Hazards Identified and potential harm it could cause	People At Risk	Actions to consider to control the risk	Actions taken and/or further recommendations	Action when?
Drowning or falling through the ice in winter.	Young children (particularly under-fives), Children with special needs, General Public Volunteer work party members.	Where possible keep pond edges clearly visible.	Edges to be kept clear of brash and long vegetation.	Ongoing
		The depth should be kept as shallow as possible whilst still maintaining the main function as a wildlife area.	Any reprofiling of the pond basin will be carried out with the aim of ensuring that the maximum water depth, positioned away from the edges, does not exceed 1.5m.	Monitor and evaluate as necessary.
		Edges of the pond should be shallow.	Pond will be maintained with gently sloping margins.	Ongoing
		Install a level marker within the pond.	A level marker displaying both metric and imperial depths from 0-1.5m has been purchased and will be installed during summer 2024.	Before Oct 2024
		Keep the pond regularly maintained to ensure that the perimeter does not become overly obscured and that the area around the pond does not deteriorate. Remove any trip hazards.	To be undertaken by volunteer work parties/Parish Council contractor.	Ongoing

East End Pond – Risk Assessment

		Install appropriate warning signage.	The H&S sign at the entrance should be edited to indicate that the park includes a pond and that young children should be supervised at all times. <i>Deep water</i> signs are not considered necessary as water levels should not exceed 1.5m.	Before Oct 2024
		Consider the provision of Life Preservation Equipment e.g. a throw line, 'reach-pole' or similar	The levels of water and ground profile are such that rescuers would be able to wade into the pond to extricate a casualty. This is likely to be more effective than the provision of LPE.	
		Volunteer work party members to conduct their own risk assessment to mitigate the risk for all work performed.	Team leaders undertake risk assessment before work parties commence any onsite activity.	
Injury through being hit by falling trees or branches	General public using the facility	Conduct regular visual assessments of tree population identifying and assessing possible risks and specifying any recommended remedial works.	Visual checks to be made by work party volunteers and Parish Council members on an ad-hoc basis. Parish Council to commission a Tree Risk Management report from qualified Arboricultural specialists every 5 years.	Tree Risk Management report undertaken 13/11/2023. Remedial works to be carried out in 2024.